Supplement 30

Business Class Trucks Service Manual **August 2003**

Enclosed are new and revised pages for your *Business Class® Trucks Service Manual.*

Major changes are as follows:

Group 15	Section 15.00 "Alternator, Delco Remy CS–130 Series" has completely updated information in the troubleshooting subject.
	Section 15.01 "Alternator, Delco Remy 21/22–SI" has completely updated information in the troubleshooting subject.
	Section 15.04 "Alternator, Nippondenso" has a new troubleshooting subject.
	Section 15.09 "Alternator, Lestek Brute 190 and 200" has completely updated information in the troubleshooting subject.
Group 20	Section 20.06 "Horton DriveMaster Fan Clutch" is new.
Group 25	Section 25.07 "Sachs Hydraulic Clutch System" is new.
Group 31	Section 31.06 "Fifth Wheel, Fontaine® H5092 Series" is new.
	Section 31.07 "Fifth Wheel, Fontaine® 6000 and 7000 No-Slack II Series" is new.
Group 32	Section 32.02 "Freightliner AirLiner Suspension" has added 10k, 12k, and 15k height control valve adjustment information. The adjustments for axle alignment has been revised to include procedures for single and tandem axles.
Group 83	Section 83.00 "Heater and Air Conditioner, R–12 Systems" has revised vendor names and phone numbers.

File Supplement 30 as follows:

Group or Section	Remove	Insert
Validity List	all pages	all pages
Preface	Title Page	Title Page
	Foreword	Foreword
	Introduction	Introduction
00.03	050	050
15.00	300	300
15.01	300	300
15.04	Contents	Contents
	—	300
15.09	300	300
20	Group Index	Group Index
20.06	—	Contents–400
25	Group Index	Group Index
25.07	—	Contents–500
31	Group Index	Group Index
31.06	—	Contents–300
31.07	—	Contents–300

Supplement 30

August 2003 Business Class Trucks Service Manual

Group or Section	Remove	Insert
32.02	110	110
	180	180
46.03	400	400
46.04	400	400
46.05	400	400
46.07	400	400
46.09	400	400
46.10	400	400
83.00	220	220
98.00	120	120
Index	all pages	all pages